

eroded reach. Photographic documentation depicting mitigation measures taken along Piney Creek South is provided by photographs 62-83 in Appendix A.